

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Madera County FCWCA

Ash And Berenda Slough Control Structures

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Revetments	A
	Concrete Foundations	A
	Closure Structures	A
	Trash Rakes	M

Fresno River Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
M	Encroachments	U
	Concrete Foundations	A

Flood Control Project Maintenance

Unit Cover Sheet

2008 Structure Inspection Results

Madera County FCWCA

Structure
Ash And Berenda Slough Control Structures

Date of Inspection	9/3/2008
DWR Inspector	Herman Phillips
Structure Rating	A

Flood Control Project Maintenance
Inspection Report - Structure 2008

Madera County FCWCA

Structure						Inspection Date	Inspector	
Ash And Berenda Slough Control Structures						09/03/2008	Herman Phillips	
RptLine	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Vegetation & Obstructions		M			°	4
							°	
2	Structures & Concrete Lined Channels	Revetments		A			°	2
							°	
3	Structures & Concrete Lined Channels	Concrete Foundations		A	The walkway on the Ash Structure has a few loose boards that should beplaced soon.		°	Y 1
							°	
4	Structures & Concrete Lined Channels	Closure Structures		A			°	5
							°	
5	Structures & Concrete Lined Channels	Trash Rakes		M			°	Y 6
							°	
6	Structures & Concrete Lined Channels	Trash Rakes		M			°	3
							°	

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Structure 2008

Madera County FCWCA

Structure	Inspection Date	Inspector
Ash And Berenda Slough Control Structures	09/03/2008	Herman Phillips

Report Line	3
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

The upstream side of the Berenda Structure .



Report Line	3
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

The downstream side of the Berenda Structure.



Report Line	3
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

photo of damaged boards on the walk way crossing the Ash slough structure located on the left bank side downstream.



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable

PO : Partially Obstructing
 CO : Completely Obstructing
 N : Not Inspected

C : Corrected

Flood Control Project Maintenance
Inspection Report - Structure 2008

Madera County FCWCA

Structure	Inspection Date	Inspector
Ash And Berenda Slough Control Structures	09/03/2008	Herman Phillips

Report Line	5
Location	
Category	Structures & Concrete Lined Channels
Item	Trash Rakes

The downstream side of the Ash Structure. Note the dense vegetation in channel.



Report Line	5
Location	
Category	Structures & Concrete Lined Channels
Item	Trash Rakes

The upstream side of the Ash structure



*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance

Unit Cover Sheet

2008 Structure Inspection Results

Madera County FCWCA

Structure
Fresno River Diversion Weir

Date of Inspection	9/3/2008
DWR Inspector	Herman Phillips
Structure Rating	M

Flood Control Project Maintenance
Inspection Report - Structure 2008

Madera County FCWCA

Structure	Inspection Date	Inspector
Fresno River Diversion Weir	09/03/2008	Herman Phillips

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Structures & Concrete Lined Channels	Encroachments		U				° Y 2 °
2	Structures & Concrete Lined Channels	Concrete Foundations		A				° Y 1 °

*** Location**

LS : Land Side
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
 M : Minimally Acceptable CO : Completely Obstructing
 U : Unacceptable N : Not Inspected

Flood Control Project Maintenance
Inspection Report - Structure 2008

Madera County FCWCA

Structure	Inspection Date	Inspector
Fresno River Diversion Weir	09/03/2008	Herman Phillips

Report Line	1
Location	
Category	Structures & Concrete Lined Channels
Item	Encroachments

Looking south at the unauthorized earthen dam placed across the upstream side of the control structure.



Report Line	2
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

View of the velocity dissipaters, stilling basin and wier. This photo shows the wild growth growing in the spilway and downstream of the dissipaters.



Report Line	2
Location	
Category	Structures & Concrete Lined Channels
Item	Concrete Foundations

Looking south at the diversion weir.



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected